

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
DC
WASH.
166-

Addendum to
Frederick Douglass House (Cedar Hill,
John Van Hook House)
1411 W Street, SE
Washington
District of Columbia

HABS No. DC-97

Photographs DC-97-1 to DC-97-9 transmitted to Library of Congress ca. 1963.

Ronald Comedy, Photographer September, 1971

DC-97-10 INTERIOR, DURING RESTORATION

DC-97-11 INTERIOR, STAIRWAY, FIRST FLOOR, DURING RESTORATION

HABS
DC,
WASH.
166-

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

ADDENDUM TO
FREDERICK DOUGLASS HOUSE
(CEDAR HILL)
(JOHN VAN HOOK HOUSE)
1411 W Street, SE
Washington
District of Columbia

HABS No. DC-97

DC-97-1 through DC-97-11 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Walter Smalling, Photographer, October 1977

DC-97-12 (CT) NORTH ELEVATION LOOKING SOUTHWEST